

cefuroxime sodium surface ih sample method

shipping requirements	Cold, dry ice
swabbing media	CleanTips swabs, 2 Large Alpha swabs, cat. TX714A, TWTexwipe

If you wish to submit a sample, please follow the sample submission procedures found at safebridge.com/laboratory/sample-submission. SafeBridge regularly develops new and custom industrial hygiene air and surface sampling methods. For more information, please call (650) 961-4820. SafeBridge Consultants, Inc. is the premier occupational health and safety and risk assessment consulting firm to the pharmaceutical, biotechnology, and fine chemical industry. Learn more at safebridge.com.