

# **lactose surface ih sample method**

|                              |                                                                                            |
|------------------------------|--------------------------------------------------------------------------------------------|
| <b>shipping requirements</b> | On ice, overnight                                                                          |
| <b>swabbing media</b>        | CleanTips Swabs TX714A, 2 swabs per sample placed into 15 ml polypropylene centrifuge tube |
| <b>swabbing solution</b>     | DI water                                                                                   |

If you wish to submit a sample, please follow the sample submission procedures found at [safebridge.com/laboratory/sample-submission](https://safebridge.com/laboratory/sample-submission). SafeBridge regularly develops new and custom industrial hygiene air and surface sampling methods. For more information, please call (650) 961-4820. SafeBridge Consultants, Inc. is the premier occupational health and safety and risk assessment consulting firm to the pharmaceutical, biotechnology, and fine chemical industry. Learn more at [safebridge.com](https://safebridge.com).