

# tenofovir df surface ih sample method

|                              |                                                              |
|------------------------------|--------------------------------------------------------------|
| <b>shipping requirements</b> | Ambient temperature                                          |
| <b>swabbing media</b>        | CleanTips swabs, 2 Large Alpha swabs, cat. TX714A, TWTexwipe |
| <b>swabbing solution</b>     | Methanol                                                     |

If you wish to submit a sample, please follow the sample submission procedures found at [safebridge.com/laboratory/sample-submission](https://safebridge.com/laboratory/sample-submission). SafeBridge regularly develops new and custom industrial hygiene air and surface sampling methods. For more information, please call (650) 961-4820. SafeBridge Consultants, Inc. is the premier occupational health and safety and risk assessment consulting firm to the pharmaceutical, biotechnology, and fine chemical industry. Learn more at [safebridge.com](https://safebridge.com).